


# East 17th Street




## EXPLANATION

- MW-9** Groundwater Monitoring Wells Installed by MJA Consulting, Inc.
- B-11** Location and Designation of Soil Boring by MJA Consulting, Inc.
- VE-10** Location and Designation of Vapor Extraction Wells.
- AS-8** Location and Designation of Air Sparging Wells.
- D** Location and Designation of Soil Borings by CJA & Associates (1/28/02).

### Notes:

1. All locations are approximate. Well locations were updated 12/15/03 by survey provided by J.M. Hanks & Associates, dated October 29, 2003.
2. N.S. = Not sampled.

- (44,000)** Total Petroleum Hydrocarbon Concentration in Groundwater in Micrograms Per Liter (µg/l).
- 10,000** Contour of Total Petroleum Hydrocarbon Concentration in Micrograms Per Liter (µg/l). Dashed Where Inferred.



**CJA C. JAMES & ASSOCIATES, INC.**  
Environmental Consultants

Client:  
**BEACON BAY AUTO WASH NO.3**  
OCHCA Case #90UT99  
481 East 17th Street, Costa Mesa, California

## SITE PLAN WITH TOTAL PETROLEUM HYDROCARBON CONCENTRATIONS IN GROUNDWATER ON JANUARY 28, 2005

Plate 4

Drawn By: H.L. Approved By: H.H. Project Number: 00445 Date: January 2005